

QUICK AND EASY DOOR REPAIR WITH BELZONA

ID: 4692

Industry: *Buildings & Structures*
Application: *WPA-Wall Problem Areas*
Substrate: *Wood*
Products: ** Belzona® 8111 (Mouldable Wood),*

Customer Location: *Housing Association, Worcester, UK*
Application Date: *September 2013*

Problem

A new door had been fitted with a new lock and catch. The position of these had to be changed leaving two cut outs in the door frame from the old lock and separate catch.



Photograph Descriptions

- * Damaged door frame ,
- * Applying Belzona® 8111 ,
- * Completed wood repair ,
- * Painted finish ,

Application Situation

Damaged door frame

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-5. A Belzona plastic applicator was used both to apply the product and as a former to create the required profile.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

The repair was carried out in less than one hour from start to finish and in one site visit. The alternative repair for the Housing Association had been replacing door frames. Far more costly and time consuming.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

