

BELZONA GIVES OLD PROPERTY NEW LEASE OF LIFE

ID: 4708

Industry: Buildings & Structures
Application: WPA-Wall Problem Areas
Substrate: Brick
Products: * Belzona® 5151 (High Build Cladding) ,

Customer Location: Farm house, Worcestershire, UK
Application Date: June 2013

Problem

Failure of the existing paint was allowing damp to penetrate into the walls leading to further deterioration. Client needed system to protect walls and approve appearance.



Photograph Descriptions

- * Surface Preparation ,
- * Application of Belzona® 3911 (PSC Conditioner) ,
- * Completed Belzona® 5151 Application. ,

Application Situation

Old farm house walls.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1. A mechanical wire brush was used over the entire surface to remove loose material. After treating with fungicidal wash the Belzona® 5151 system was applied.

Belzona Facts

Due to the contractor using Belzona products on a number of very successful applications within the social housing sector they were able to demonstrate the effectiveness of the Belzona® 5151 system to the client.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

