# BELZONA REPAIRS PST AT WATER TREATMENT PLANT

ID: 4711

Industry: Water / Wastewater Customer Location: Water treatment plant, Gloucestershire,

UK

Application: FPA-Floor Problem Areas Application Date: October 2012

Substrate: Concrete

Products: \* Belzona® 4131 (Magma Screed),

\* Belzona® 2211 (MP Hi-Build Elastomer),

#### **Problem**

Walls of the running track had become badly worn and damaged over time due to rotation of the distributor. Some areas had been unsuccessfully repaired in the past.









## **Photograph Descriptions**

- \* Damaged running track and failed previous repairs,
- \* Shuttering boards being installed,
- \* Completed repair back in service,
- \* Repaired areas 12 months on,

### **Application Situation**

Concrete wall of a Primary Settlement Tank (PST)

## **Application Method**

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 & FPA-6. Once the surface was prepared, shuttering boards were fitted to the side walls to enable the Belzona® 4131 to be applied to accurate levels. Once the Belzona 4131 had cured the boards were removed and expansion joints cut into the repaired areas. These joints were then sealed with Belzona® 2211.

### **Belzona Facts**

The Belzona solution was chosen due to the quick turnaround compared to other methods. Also the failure of the previous patch

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

repairs led them to the need for a permanent repair. The longevity of the Belzona solution backed up by case histories supported the proposal.	
For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com	