

# BELZONA SOLVES FINLOCK GUTTER ISSUES

ID: 4715

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Concrete*  
Products: *\* Belzona 3131 (WG Membrane) Belzona 4141 (Magma Build) ,*

Customer Location: *Housing Association, Herefordshire, UK*  
Application Date: *March 2013*

## Problem

*Finlock gutters had begun to leak into the properties.*



## Photograph Descriptions

\* 1. Before Application 2. Removal of existing liners 3. Application in progress 4. Completed Application. ,

## Application Situation

Rows of Finlock Gutters on Housing Association Properties.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-6 and RPA-11. Any damaged areas of concrete were repaired using Belzona 4141 followed by complete coating with the reinforced Belzona 3131 system.

## Belzona Facts

The housing association had tried a number of different solutions including metal liners, felt and another liquid applied product. Belzona has a long successful history of repairing and sealing finlock gutters.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve