

# BELZONA MAKES RAMP SAFE

ID: 4729

## Industry:

Application: FPA-Floor Problem Areas

Substrate: Steel chequerplate.

Products: \* Belzona® 1821 (Fluid Metal) ,

Customer Location: Local Authority, Derbyshire, UK

Application Date: 2010

## Problem

*The chequerplate had become polished and slippery especially when wet.*



## Photograph Descriptions

- \* Long chequerplate walkway before application ,
- \* Chequerplate showing preparation and correct masking to provide chevron pattern ,
- \* Application by brush with immediate removal of masking tape ,
- \* Finished job ,

## Application Situation

A long steel chequerplate access walkway located alongside the community college allowing access to two buildings.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. After preparing the substrate and masking the chevron pattern on the surface the Belzona® 1821 was applied and aggregate tamped into the surface before removing the masking and allowing system to cure overnight.

## Belzona Facts

Even though chequerplate is known to have a pattern across its surface this had become polished and had become very slippery especially when wet. The Belzona® 1821 grip system applied along the surface of the chequerplate provided added positive grip and safety for pedestrians.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve