

BELZONA USED IN REFURBISHMENT OF VICTORIAN SCHOOL

ID: 4743

Industry:

Application: WPA-Wall Problem Areas

Substrate: Brick and Stonework

Products: * Belzona 5151 (Hi-Build Cladding) ,
* Belzona 4141 (Magma-Build) ,
* Belzona 5122 (Clear Cladding Concentrate) ,

Customer Location: Local authority, Mansfield, UK

Application Date: 2002

Problem

Atmospheric pollution and weathering had led to degraded, porous dirty stonework and brickwork giving unsightly appearance.



Photograph Descriptions

- * Building before cleaning process ,
- * After power washing ,
- * Work underway on repairing stonework ,
- * Completed application ,

Application Situation

Victorian school building

Application Method

Application was carried out in accordance with Belzona System Leaflets WPA-1, WPA-4 & WPA-8. After power washing to remove all dirt and deteriorated brick and stone, damaged bricks were replaced and stonework repaired with Belzona 4141. Belzona 5151 used as protective coating on stonework and remaining porous surfaces treated with Belzona 5122.

Belzona Facts

Client had already used us on a number of other projects and was happy with the Belzona systems. The Belzona repairs were cost effective and the protective coatings will maintain the cleaned facades reducing future atmospheric weathering.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve