

BELZONA® PREVENTS LEAKS INTO ELECTRICAL ROOM

ID: 4786

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Brick and Concrete*
Products: ** Belzona 3121 (MR7 Membrane) ,*

Customer Location: *Hotel Chain, Vancouver, BC, Canada*
Application Date: *October 2009*

Problem

The leak was over the hotel electrical room causing periodic power disruptions.



Photograph Descriptions

* 1. Surface preparation underway 2. The area was masked off before the 1st coat of Belzona 3121 was applied 3. A 2nd coat of Belzona 3121 was applied along with reinforcing sheet to ensure that the gap was adequately bridged. A 3rd coat was applied to complete the application. ,

Application Situation

A leak had developed between the brick wall and the parking garage floor.

Application Method

Application was carried out using a modified version of Belzona System Leaflet RPA-1. The area along the wall and concrete floor was ground with a Vac-grinder to ensure a good surface for bonding before applying the Belzona 3121 system.

Belzona Facts

This use of Belzona 3121 allowed for a quick turn around and minimal disruption to the hotel vehicle traffic in the area.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025