


BELZONA RINGS A TUNE

ID: 484

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Concrete*
Products: ** Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *University in Southern California, USA*
Application Date: *August 2004*

Problem
Roof leaks



Photograph Descriptions

- * The bell tower ,
- * Leaks were allowing water to ingress the bells bellow ,
- * Problems clearly evident ,
- * Completed roof repair ,

Application Situation

161-foot bell tower

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8.

Belzona Facts

The roof area is approximately 30 square feet with a hatch opening. Customer had been advised that the roof should be removed to be repaired. Belzona® 3111 was used to repair the roof in place, saving significant amounts of money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025