

VULCANIZING COMPANY SAVES TIME AND MONEY

ID: 4870

Industry: *Mining & Quarrying*

Customer Location: *Vulcanizing Company, Southwest Scotland.*

Application: *SHM-Solids Handling Machinery*


Application Date: *January 1996*

Substrate: *Rubber*

Products: ** Belzona 2311 (SR Elastomer) ,
* Belzona 2911 (Elastomer QD Conditioner) ,
* Belzona 9341 (Reinforcing Tape) ,*

Problem

The tire had a cut which penetrated right through the wall, requiring repairs to be performed not only on the outside but on the inside of the tire as well.



Photograph Descriptions

- * Inside portion of the tire before the repair ,
- * Surface preparation in progress ,
- * Inside repair near completion ,
- * Finished repair to the outside ,

Application Situation

Off-road tractor's tire

Application Method

The affected areas (both inside and outside of the tire) were abraded then fully cleaned and degreased. Then, the substrate was conditioned using Belzona 2911 (Elastomer QD Conditioner). Belzona 2311 (SR Elastomer) was then mixed and applied incorporating Belzona 9341 (Reinforcing Tape) to the area around the damage.

Belzona Facts

The tire was returned to service and is performing as good as new. This Belzona repair was quick and easy to complete, saving time

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



and money to the end client.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

