

LEAKY ROOF REPAIRED WITH BELZONA DODGING A THUNDERSTORM

ID: 4885

Industry:

Customer Location: *Coal Mine, USA*

Application: *RPA-Roof Problem Areas*

Application Date: *May 2006*

Substrate: *Steel*

Products: ** Belzona 3111 (Flexible Membrane) ,*

Problem

The warehouse roof leaked for over 20 years with 5 different contractors trying to fix it.



Photograph Descriptions

- * Problem area ,
- * Application in progress ,
- * Complete application ,

Application Situation

Roof leak

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

Belzona Facts

Belzona 3111 was used, dodging a thunderstorm in 3 weeks. It has not leaked a drop in 8 years now.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

