DAMAGED FLOORING IN JAIL KITCHEN

ID: 4923

Industry:Buildings & StructuresCustomer Location: Ontario, CanadaApplication:FPA-Floor Problem AreasApplication Date: January 2014

Substrate: Ceramic tile

Products: * Belzona 4191 (Magma TX Conditioner),

* Belzona 4131 (Magma-Screed),

Problem

The kitchen floor tiles were undermined by water, penetrating the grout and loosening the tile adhesive causing them to lift and break. This created a Health and Safety issue.







Photograph Descriptions

- * Complete preparation,
- * Kitchen floor prior to application,
- * Complete application,

Application Situation

Kitchen floor tiles

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. To prepare the area, the broken tiles were removed down to the concrete and cleared of any loose material or contamination and abraded to expose the aggregate. Concrete was treated with a layer of Belzona 4191 pior to the Belzona 4131 application. Belzona 4131 was applied to the area initially spreading to a general level using normal screeding technique and then smoothing off using a steel float in accordance with Belzona Instructions For Use.

Belzona Facts

Belzona 4131 once fully cured will provide excellent protection from the effects of pedestrian traffic and chemicals used in the cleaning process. The system is optimised for rapid cure and accepts pedestrian traffic in as little as 1 hour, a requirement of the

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®

application as the kitchen could only be closed for a maximum of 10 hours a day.