

RUBBER LINER IN SLURRY PUMP REPAIRED WITH BELZONA

ID: 4935

Industry: Mining & Quarrying
Application: SHM-Solids Handling Machinery

Customer Location: Quarry, Israel
Application Date: February 2014

Substrate: Rubber
Products: * Belzona 2311 (SR Elastomer) ,

Problem

The rubber liner had suffered local damage resulting in an operational shutdown.



Photograph Descriptions

- * Damaged rubber liner ,
- * The Warman 10/8M pump ,
- * Damaged area Conditioned with Belzona 2911 (Elastomer QD Conditioner) ,
- * Rubber liner after application of Belzona 2311 ,

Application Situation

Rubber lined Warman 10/8M slurry pump.

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet SHM-9.

Belzona Facts

The costumer was able to run the pump the same day saving shutdown costs of 7 days whilst waiting for new replacement liner.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve