

# RUBBER LINER IN SLURRY PUMP REPAIRED WITH BELZONA

ID: 4935

Industry: *Mining & Quarrying*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Quarry, Israel*  
Application Date: *February 2014*

Substrate: *Rubber*  
Products: *\* Belzona 2311 (SR Elastomer) ,*

## Problem

*The rubber liner had suffered local damage resulting in an operational shutdown.*



## Photograph Descriptions

- \* Damaged rubber liner ,
- \* The Warman 10/8M pump ,
- \* Damaged area Conditioned with Belzona 2911 (Elastomer QD Conditioner) ,
- \* Rubber liner after application of Belzona 2311 ,

## Application Situation

Rubber lined Warman 10/8M slurry pump.

## Application Method

Application was carried out in accordance with Belzona Know How System Leaflet SHM-9.

## Belzona Facts

The customer was able to run the pump the same day saving shutdown costs of 7 days whilst waiting for new replacement liner.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve