

SUCCESSFUL BELZONA REFURBISHMENT OF GUTTER

ID: 4975

Industry:	Buildings & Structures	Customer Location:	Interior furnishings showroom, Northern Ireland
Application:	RPA-Roof Problem Areas	Application Date:	April 2014
Substrate:	Powder Coated Aluminium		
Products:	* Belzona 3111 (Flexible Membrane) ,		

Problem

The client has had consistent water ingress issues from the aluminium gutters, despite repeated attempts to seal the gutter joints and seams with silicone and bitumen products. The showroom area has suffered water damage on a regular basis.



Photograph Descriptions

- * Gutters before application ,
- * Conditioner applied ,
- * Completed system ,

Application Situation

Client is the owner of a large interior furnishings showroom, with the premises now approaching 15 years of age.

Application Method

After thorough cleaning and drying of the substrate, application was carried out according with Belzona System Leaflet RPA-6. Belzona 3921 (GSC surface conditioner) was used to give optimum adhesion and a fully reinforced system incorporating Belzona 9311 (Reinforcing sheet) in the Belzona 3111 first coat was applied.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Belzona Facts

After "quick fix" alternatives of silicone and bitumen patching had failed, the client realised a Project orientated approach with a reputable system applied to the entire 95lm of gutters would offer a long term solution, and thus result in the best value protection for his asset.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2024