SUCCESSFUL BELZONA REFURBISHMENT OF GUTTER

ID: 4975

Industry: Buildings & Structures Customer Location: Interior furnishings showroom, Northern

Ireland

Application: RPA-Roof Problem Areas Application Date: April 2014

Substrate: Powder Coated Aluminium

Products: * Belzona 3111 (Flexible Membrane),

Problem

The client has had consistent water ingress issues from the aluminium gutters, despite repeated attempts to seal the gutter joints and seams with silicone and bitumen products. The showroom area has suffered water damage on a regular basis.







Photograph Descriptions

- * Gutters before application ,
- * Conditioner applied ,
- * Completed system,

Application Situation

Client is the owner of a large interior furnishings showroom, with the premises now approaching 15 years of age.

Application Method

After thorough cleaning and drying of the substrate, application was carried out according with Belzona System Leaflet RPA-6.

Belzona 3921 (GSC surface conditioner) was used to give optimum adhesion and a fully reinforced system incorporating Belzona 9311 (Reinforcing sheet) in the Belzona 3111 first coat was applied.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

Belzona Facts

After "quick fix" alternatives of silicone and bitumen patching had failed, the client realised a Project orientated approach with a reputable system applied to the entire 95lm of gutters would offer a long term solution, and thus result in the best value protection for his asset

www.belzona.com