

# BELZONA WAREHOUSE FLOOR

ID: 5

**Industry:** Chemical & Petrochemical  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona® 4131 (Magma screed) ,

**Customer Location:** Chemical plant in Louisiana  
**Application Date:** April 1995

## Problem

*Deteriorated floor was creating a safety hazard.*



## Photograph Descriptions

- \* Surface preparation to the damaged area in progress. ,
- \* The completed repair. ,

## Application Situation

Floor in warehouse.

## Application Method

The application was carried out in accordance Belzona Know-How Leaflet FPA-1.

## Belzona Facts

This is a long term solution to the problem. After three years in operation, the floor is in excellent condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve