

BELZONA WAREHOUSE FLOOR


ID: 5

Industry: Chemical & Petrochemical
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma screed) ,

Customer Location: Chemical plant in Louisiana
Application Date: April 1995

Problem

Deteriorated floor was creating a safety hazard.



Photograph Descriptions

- * Surface preparation to the damaged area in progress. ,
- * The completed repair. ,

Application Situation

Floor in warehouse.

Application Method

The application was carried out in accordance Belzona Know-How Leaflet FPA-1.

Belzona Facts

This is a long term solution to the problem. After three years in operation, the floor is in excellent condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve