

Belzona® 2111 (D&A Hi Build Elastomer) Saves Utility


ID: 503

Industry: Power
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Rubber
Products: * Belzona® 2111 (D&A Hi Build Elastomer) ,
* Belzona® 2911 (QD Conditioner) ,

Customer Location: Power Authority, San Antonio, Texas USA
Application Date: 2002

Problem

Inspection revealed severe corrosion in spots on floor. Customer needed fast, cost effective repair.



Photograph Descriptions

- * Lime slurry tank showing corrosion in rubber liner ,
- * Another view of corrosion ,
- * Close up view of corrosion ,
- * Belzona® 2111 patch complete ,

Application Situation

Rubber lined lime slurry tank

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

Belzona Facts

Hot vulcanization and liner replacement had been considered but were judged too time consuming and costly. Belzona® 2111 was chosen for its great abrasion and chemical resistance, as well as its ease of application. Repair still in excellent condition after three years of service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve