

Belzona Protects Stadium

ID: 506

Industry: *Buildings & Structures*

Customer Location: *St. Louis University, St. Louis, Missouri
USA*

Application: *RPA-Roof Problem Areas*



Application Date: *April 2005*

Substrate: *Stone*

Products: ** Belzona® 3111 (Flexible Membrane),*

Problem

Wall caps had deteriorated to the point of either needing repairing or replacing.



Photograph Descriptions

- * Overall view of stands ,
- * Close up of typical damaged block ,
- * Completed south wall area ,
- * Completed north wall area ,

Application Situation

Stone wall caps

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet RPA-11.

Belzona Facts

Replacement cost in this situation was astronomical; the Belzona solution offered a cost effective alternative. The Belzona® 3111 was tinted to match the color of the original stone.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve