

# Belzona Protects Stadium

ID: 506

Industry: *Buildings & Structures*

Customer Location: *St. Louis University, St. Louis, Missouri  
USA*

Application: *RPA-Roof Problem Areas*

Application Date: *April 2005*

Substrate: *Stone*

Products: *\* Belzona® 3111 (Flexible Membrane),*

## Problem

*Wall caps had deteriorated to the point of either needing repairing or replacing.*



## Photograph Descriptions

- \* Overall view of stands ,
- \* Close up of typical damaged block ,
- \* Completed south wall area ,
- \* Completed north wall area ,

## Application Situation

Stone wall caps

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet RPA-11.

## Belzona Facts

Replacement cost in this situation was astronomical; the Belzona solution offered a cost effective alternative. The Belzona® 3111 was tinted to match the color of the original stone.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

