

BELZONA REBUILDS DAMAGED STONework

ID: 5083

Industry:

Application: WPA-Wall Problem Areas

Substrate: Stone

Products: * Belzona 4141 (Magma-Build) ,

Customer Location: School, West Yorkshire, UK

Application Date: Summer 2013

Problem

Weathered stonework needed rebuilding to improve appearance and remove risk of falling debris.



Photograph Descriptions

- * Before application ,
- * Local repair to corbel with shape detail ,
- * Completed application to corbel ,
- * Completed application to window sill. ,

Application Situation

Weathered stonework on school building.

Application Method

The application was carried out in accordance with Belzona System Leaflet WPA-4. The substrate was hand prepared to remove any loose material. This was followed by application of Belzona 4911 (TX Conditioner) before Belzona 4141 was applied. This material was shaped by hand to match in with the existing stonework.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Due to the health and safety implications of the situation, the client required a solution to be carried out as soon as possible in order to eliminate any potential accidents. Belzona were able to facilitate this, carrying out a site survey and conducting the application over a course of just two weeks.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

