

BELZONA RUBBER LINED VALVE REPAIR

ID: 5086

Industry: Power

Customer Location: Regional Energy Company, Pancevo, Serbia

Application: VPF-Valves, Pipes and Fittings

Application Date: June 2014

Substrate: Rubber

Products: * Belzona 2311 (SR Elastomer),

Problem

Valve sealing surface had deteriorated over the years causing inefficiency in stopping flow of water



Photograph Descriptions

- * Valve damage marked up ,
- * Prepared surface ,
- * Belzona 2311 application completed ,
- * Assembled valve to undergo pressure test ,

Application Situation

Water control valve

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-5

Belzona Facts

Belzona repair was cost effective and allowed valve to be quickly returned to service. Fast curing Belzona 2311 was only solution available to the customer in the downtime available.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve