

# BELZONA RUBBER LINED VALVE REPAIR

ID: 5086

Industry: Power

Customer Location: Regional Energy Company, Pancevo,  
Serbia

Application: VPF-Valves, Pipes and Fittings

Application Date: June 2014

Substrate: Rubber

Products: \* Belzona 2311 (SR Elastomer) ,

## Problem

Valve sealing surface had deteriorated over the years causing inefficiency in stopping flow of water



## Photograph Descriptions

- \* Valve damage marked up ,
- \* Prepared surface ,
- \* Belzona 2311 application completed ,
- \* Assembled valve to undergo pressure test ,

## Application Situation

Water control valve

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-5

## Belzona Facts

Belzona repair was cost effective and allowed valve to be quickly returned to service. Fast curing Belzona 2311 was only solution available to the customer in the downtime available.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve