

CORRODED AND CRACKED PIPEWORK FIXED WITH BELZONA

ID: 5106

Industry: General Industry
Application: VPF-Valves, Pipes and Fittings
Substrate: Steel
Products: * Belzona 1221 (Super E-Metal) ,
* Belzona 1161 (Super UW-Metal) ,

Customer Location: Manufacturing company, Slough, UK
Application Date: May 2014

Problem

The pipe had corroded and cracked, leaking 10% Sodium Hydroxide.



Photograph Descriptions

- * 1&2. Cracked and corroded pipework ,
- * 3. Completed application ,

Application Situation

Pipework at global paints and coatings company.

Application Method

Application was carried out in accordance with Belzona System Leaflet VPF-11. Surface preparation was carried out using an MBX Bristle Blaster as grit blasting was not an option. After stemming weep, the pipe was wrapped with Belzona 1161 incorporating Belzona 9341 (Reinforcement Tape).

Belzona Facts

The Belzona solution ensured the repair was carried out in as little amount of time as possible (just 4 hours), keeping downtime to a minimum.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve