

# BELZONA WEATHERPROOFS TWO SUGAR SILOS

ID: 5175

Industry: *Food & Drink*  
 Application: *WPA-Wall Problem Areas*  
 Substrate: *Concrete*  
 Products: *\* Belzona 3111 (Flexible Membrane),*

Customer Location: *Sugar factory, Northern France*  
 Application Date: *2014*

## Problem

*Infiltration of water into the tank through the porous concrete.*



## Photograph Descriptions

- \* General view of the sugar plant ,
- \* On-going application ,
- \* Finished application ,
- \* 6 years after the application ,

## Application Situation

Two sugar silos within the sugar factory required weatherproofing

## Application Method

Application was carried out in accordance with Belzona System Leaflet WPA-1. The work was completed by applying the system in vertical stripes of 6 meter width.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
 FS 695214  
 ISO 14001:2015  
 EMS 695213

Belzona products are  
 manufactured under an ISO  
 9000 Registered Quality  
 Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
 Repair • Protect • Improve

The Belzona 3111 system is proven to provide excellent long term weatherproofing of substrates. The application was carried out in 10 weeks with a team of 7 applicators. The silos have been revisited after 2 years and 6 years later, the application was still in perfect condition.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

