

BELZONA REPAIRS DAMAGED CLIP JOINT

ID: 5181


Industry: *General Industry*
Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*
Application Date: *August 1996*

Substrate: *Mild steel and rubber.*
Products: ** Belzona 2311 (SR Elastomer) ,*

Problem

Clip joint had started to separate and tear.



Photograph Descriptions

- * View of damaged clip joint ,
- * Completed application. ,

Application Situation

Clip joint tear.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-4

Belzona Facts

Using Belzona 2311 SR Elastomer allowed the belt to be repaired in place during a lunch break eliminating downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Copyright © Belzona International Limited 2024