

BELZONA REPAIRS CABLE REINFORCED CONVEYOR BELT

ID: 5184


Industry: *General Industry*
Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*
Application Date: *August 1996*

Substrate: *Rubber*
Products: ** Belzona 2311 (SR Elastomer) ,*

Problem

Cable stayed belt would develop cracks over a period of time.



Photograph Descriptions

- * View of preparation in progress ,
- * Close-up of one of the repair areas ,
- * Completed application. ,

Application Situation

Cracked cable stayed belt

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1

Belzona Facts

Because of its rapid set-up time, coupled with its quick development of mechanical strength, Belzona 2311 allowed repairs to be made to the belt during unscheduled or short shut-downs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024