

BELZONA REPAIRS CABLE REINFORCED CONVEYOR BELT

ID: 5184

Industry: *General Industry*

Customer Location: *BC, Canada*

Application: *SHM-Solids Handling Machinery*


Application Date: *August 1996*

Substrate: *Rubber*

Products: ** Belzona 2311 (SR Elastomer) ,*

Problem

Cable stayed belt would develop cracks over a period of time.



Photograph Descriptions

- * View of preparation in progress ,
- * Close-up of one of the repair areas ,
- * Completed application. ,

Application Situation

Cracked cable stayed belt

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1

Belzona Facts

Because of its rapid set-up time, coupled with its quick development of mechanical strength, Belzona 2311 allowed repairs to be made to the belt during unscheduled or short shut-downs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

