

BELZONA REPAIRS RUBBER LINED SLURRY PUMP

ID: 5189

Industry: *General Industry*

Customer Location: *BC, Canada*

Application: *SHM-Solids Handling Machinery*

Application Date: *1990*

Substrate: *Steel/ Rubber*

Products: ** Belzona 2111 (D&A Hi-Build Elastomer) ,*

Problem

A hole had worn into the rubber lining in a number of areas from the coal slurry and had started to erode the metal casing.



Photograph Descriptions

- * Preparation of the damaged areas in progress ,
- * Preparation completed ,
- * Rubber liner rebuilt ,

Application Situation

Rubber lining on a slurry pump

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-11

Belzona Facts

The use of Belzona allowed localized repairs to be executed with a minimal amount of downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve