

BELZONA REPAIRS RUBBER LINED SLURRY PUMP

ID: 5189

Industry: General Industry

Customer Location: BC, Canada

Application: SHM-Solids Handling Machinery

Application Date: 1990

Substrate: Steel/ Rubber

Products: * Belzona 2111 (D&A Hi-Build Elastomer) ,

Problem

A hole had worn into the rubber lining in a number of areas from the coal slurry and had started to erode the metal casing.



Photograph Descriptions

- * Preparation of the damaged areas in progress ,
- * Preparation completed ,
- * Rubber liner rebuilt ,

Application Situation

Rubber lining on a slurry pump

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-11

Belzona Facts

The use of Belzona allowed localized repairs to be executed with a minimal amount of downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024