

BELZONA 2311 (SR ELASTOMER) USED FOR EMERGENCY REPAIRS

ID: 5197

Industry: *Mining & Quarrying*
Application: *SHM-Solids Handling Machinery*

Customer Location: *BC, Canada*
Application Date: *2000*

Substrate: *Rubber*
Products: ** Belzona 2311 (SR Elastomer) ,*

Problem

A small cut had developed in a section of the belt



Photograph Descriptions

- * View of the cut in the belt ,
- * Initial preparation underway ,
- * The loose piece of belting has been cut away and area around it roughed up with a special roughing tool ,
- * Repair in progress ,

Application Situation

Belt repair in gravel pit

Application Method

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1

Belzona Facts

The use of Belzona 2311 allowed the yard to repair the damage before it became more serious. The quick setting properties of the repair material also allowed the repair to be completed during a lunch break ensuring no downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve