BELZONA 1811 CERAMIC CARBIDE EXTENDS LIFE OF PUMP CASING

ID: 5198

Industry: Mining & Quarrying Customer Location: BC, Canada
Application: CEP-Centrifugal Pumps Application Date: June 2000

Substrate: Stainless steel

Products: * Belzona 1811 (Ceramic Carbide),

Problem

Pumping drainage water from a gravel pit has a high percentage of entrained solids causing major erosion damage to pumps







Photograph Descriptions

- * View of Pump,
- * Close-up of pump showing extent of erosion ,
- * The internal surfaces of the pump casing are protected with Belzona 1811,

Application Situation

Erosion on gravel slurry pump

Application Method

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-1

Belzona Facts

Coating the internal surfaces with a sacrificial coating such as Belzona 1811 ensures that the pump casing can be recycled many times over

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve