

BELZONA REPAIRS A CONDENSER TANK IN A FREEZER ROOM

ID: 5207

Industry: *Food & Drink*

Customer Location: *New England, USA*

Application: *TCC-Tanks and Chemical Containment Areas*

Application Date: *January 2014*

Substrate: *Steel*

Products: ** Belzona 1111 (Super Metal)
Belzona 5811 (Immersion Grade) ,*

Problem

The customer had a leaking sump tank on the floor of a frozen food warehouse, creating hazardous conditions.



Photograph Descriptions

- * Overview of the sump tank ,
- * Evidence of the leak ,
- * Weld seams and pittings filled with Belzona 1111 ,
- * Overcoating with Belzona 5811 ,

Application Situation

Sump tank leaking on engine room floor of a frozen food warehouse.

Application Method

The surface preparation was carried out by blast cleaning the lower 4 feet of the tank and floor. Corrosion holes and pittings were located mainly in weld seams areas. The holes were filled with Belzona 1111 and overcoated with Belzona 5811. The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

Belzona Facts

The customer priced out the cost of purchasing a new tank with the associated piping and labor. The estimated delivery time for the tank would take months. Additionally, the cost would make the replacement a capital budget item, which required corporate approval. The frozen food warehouse operates 24/7, 365 days per year, with millions of dollars of inventory. The freezer's building could not be shut down. The Belzona repair was completed in 2 days during the coldest time of winter so "thawing" would not be an issue.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

