

# BELZONA PROTECTS STRUCTURAL STEEL OF A PAPER MACHINE

ID: 5208

Industry: *Pulp & Paper*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Steel*  
Products: *\* Belzona 1121 (Super XL-Metal) ,  
\* Belzona 5811 (Immersion Grade) ,*

Customer Location: *New England, USA*  
Application Date: *Summer 2014*

## Problem

*The paper machine structural steel was severely corroded and in need of corrosion protection.*



## Photograph Descriptions

- \* Section of paper machine press ,
- \* Paper machine name plate with corrosion ,
- \* Close-up view of corrosion ,
- \* Completed application ,

## Application Situation

Structural steel on a section of a Valmet paper machine press.

## Application Method

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Hand tools, such as needle guns and grinders, were used for surface preparation before smoothing with Belzona 1121 and overcoating with Belzona 5811. The application was carried out with a modified version of Belzona Know-How System Leaflet TCC-5.

## Belzona Facts

Paper machine rolls are scheduled for infrequent removal during scheduled and planned maintenance outages. It was difficult to access the interior sections of the paper machine with rolls in place. The machine was shut down for 1 week in the summer time and the rolls were removed. The customer has previously used Belzona for other repairs and was impressed with the applicators and product.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

