

BELZONA REPAIRS AND PROTECTS DAMAGED DRAINS

ID: 5212

Industry: *General Industry*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: ** Belzona 4111 (Magma-Quartz),*

Customer Location: *ON, Canada*
Application Date: *June 2013*

Problem

The edges of the floor drain were breaking due to a combination of chemical attack and physical damage.



Photograph Descriptions

- * Floor drain prior to application ,
- * Preparation in process ,
- * Application in process ,
- * Completed application ,

Application Situation

Floor drain.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 for rebuilding worn or damaged floor surfaces. The surface was prepared by removing any existing coating and loose material or contamination. Belzona 4111 was applied to the floor drain edges with a stiff brush, in accordance with Belzona's Instructions For Use.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Belzona 4111 is resistant to all environmental attack and has outstanding chemical resistance. The system does not absorb water or chemicals and can resist pedestrian traffic in four hours.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

