

BELZONA SAVES CENTRIFUGAL PUMP FROM REPLACEMENT


ID: 5221

Industry: Food & Drink
Application: CEP-Centrifugal Pumps
Substrate: Cast Iron
Products: * Belzona 1341 (Supermetalglide) ,

Customer Location: WA, USA
Application Date: 1992

Problem

Erosion/Corrosion was eating away this water pump at a fruit processing company, causing it to pump less water than was required. It was then pulled from the scrap pile.



Photograph Descriptions

- * Damaged Cornell pump ,
- * Coating of impeller ,
- * Coating of pump casing ,

Application Situation

Centrifugal pump.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-10. The centrifugal pump was rebuilt to improve efficiency.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

The customer was ready to replace the pump because it just wasn't pumping enough water. Belzona 1341 improved the volume, enough to satisfy their needs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

