

# BELZONA SAVES CENTRIFUGAL PUMP FROM REPLACEMENT


ID: 5221

Industry: Food & Drink  
Application: CEP-Centrifugal Pumps  
Substrate: Cast Iron  
Products: \* Belzona 1341 (Supermetalgilde) ,

Customer Location: WA, USA  
Application Date: 1992

## Problem

Erosion/Corrosion was eating away this water pump at a fruit processing company, causing it to pump less water than was required. It was then pulled from the scrap pile.



## Photograph Descriptions

- \* Damaged Cornell pump ,
- \* Coating of impeller ,
- \* Coating of pump casing ,

## Application Situation

Centrifugal pump.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-10. The centrifugal pump was rebuilt to improve efficiency.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

The customer was ready to replace the pump because it just wasn't pumping enough water. Belzona 1341 improved the volume, enough to satisfy their needs.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

