

# BELZONA PROTECTS AND COATS PUMPS


ID: 5226

Industry: Power  
Application: CEP-Centrifugal Pumps  
Substrate: Steel and cast iron  
Products: \* Belzona 1311 (Ceramic R-Metal) ,  
\* Belzona 1341 (Supermetalglide) ,

Customer Location: MO, USA  
Application Date: March 2011

## Problem

The customer wanted to re-coat the pump although it showed very little sign of wear.



## Photograph Descriptions

- \* View of the Energy Company ,
- \* Previous application by Belzona ,
- \* Preparing the product for application ,
- \* Completed application ,

## Application Situation

During a scheduled maintenance outage, the customer wanted a pump that was previously protected with Belzona to be remediated while it was out for inspection. Note: this pump was still performing as expected.

## Application Method

All of the equipment receiving the Belzona coating was grit blasted with Black Beauty and then cleaned. Any severe pitting and erosion was addressed by rebuilding with Belzona 1311 and finished with two coats of Belzona 1341, the known pump-efficiency enhancement system. The application was carried out in accordance with Belzona Know-How System Leaflets CEP-3 & CEP-5.

## Belzona Facts

Belzona 1341 has proven to withstand many of in-service hours and years for this customer. Knowing the confidence our customer places in Belzona allows us the many opportunities to continue providing products and services for the years to come.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve