

BELZONA SAVES PUMP FROM REPLACEMENT

ID: 5231

Industry: Fluid Flow
Application: CEP-Centrifugal Pumps
Substrate: Cast iron and Steel
Products: * Belzona 1341 (Supermetalgilde) ,
* Belzona 1121 (Super XL-Metal) ,

Customer Location: MO, USA
Application Date: December 2003

Problem

The pumps from one of this well-known amusement park's water rides had badly corroded with severe loss of metal. The corrosion was so thick that the pumps required grit blasting three times to achieve a proper profile. A solution was sorely needed.



Photograph Descriptions

- * Overview of the pump ,
- * Sever corrosion damage to the pump ,
- * Completed application ,
- * Completed application ,

Application Situation

Upon inspection, the pump was taken out of service and the customer requested a Belzona consultant to provide a bid to remediate the equipment on-site.

Application Method

The most severe corrosion areas were repaired with Belzona 1121 followed by two coats of Belzona 1341 to provide a long-lasting, super slick surface. The application was carried out in accordance with Belzona Know-How System Leaflets CEP-1 & CEP-10.

Belzona Facts

The Belzona solution saved World's of Fun from the cost and inconvenience of total replacement. The solution was provided at a fraction of the price of replacement. With Belzona, these pumps will operate efficiently for many, many years to come.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2025

