

LOADING DOCK DRAIN COATED WITH BELZONA


ID: 5242

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 5811 (Immersion Grade) ,

Customer Location: Mississauga, ON, Canada
Application Date: September 2013

Problem

The existing coating had failed, causing blockage of the drain.



Photograph Descriptions

- * Prior to application ,
- * Preparation in progress ,
- * Application in progress ,
- * Completed application ,

Application Situation

Loading dock drain.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3 for protecting floors and drains against chemical attack. The surface was prepared for application by removing the existing coating and cleaned with a high pressure washer. Belzona 5811 was applied as a two coat system with a short bristle brush.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona 5811 is a brush or spray applied coating that has excellent chemical resistance and provides outstanding protection from the effects of salt water, acid, alkalis, alcohol, hydrocarbon and the environment. This product can be applied to virtually any surface including cast iron, stainless steel, brass, copper, concrete, wood, fibreglass and aluminium.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

