# STEEL OF A RAILWAY PROTECTED WITH BELZONA

ID: 5253

Industry: Transport

Application: FPA-Floor Problem Areas

Substrate: Steel

Products: \* Belzona 4151 (Magma-Quartz Resin),

Problem

Corrosion on the steel of a railway.







Customer Location: Kitchener, ON, Canada

Application Date: March 2013



## **Photograph Descriptions**

- \* Prior to application,
- \* Preparation in progress,
- \* Preparation in progress,
- \* Completed application,

### **Application Situation**

Railway at a museum.

### **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3 for protecting floors and drains against chemical attack. A MBX bristle blaster was used to remove any rust and to prepare the surface for application. Belzona 4151 was brush applied in accordance with Belzona Instructions For Use.

#### **Belzona Facts**

Belzona 4151 is a two-component system that provides a tough, seamless coating suitable for protecting various substrates from moisture ingress, chemical attack and resistance to environmental attack. Belzona 4151 can be applied and cured under adverse conditions and has excellent adhesion to many substrates.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve