

# BELZONA REPAIRS RUBBER TRACK

ID: 5257

Industry: General Industry

Application: SHM-Solids Handling Machinery

Customer Location: Washington, USA


Application Date: 1993

Substrate: Rubber

Products: \* Belzona 2111 (D & A Hi-Build Elastomer),

## Problem

*The exposed fabric will wick in water and rot, causing the track to weaken and require replacement.*



## Photograph Descriptions

- \* Caterpillar showing track ,
- \* Close up of the cut in the track ,
- \* Prepared and conditioned cut ,
- \* Completed application ,

## Application Situation

The rubber track was cut open, exposing the fabric.

## Application Method

The cut on the track was positioned so the cut was open. The rubber was roughened and Belzona 2111 was applied in accordance with Belzona Know-How System Leaflet SHM-15.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Belzona Facts

Protecting the fabric has extended the life of the track, saving thousands of dollars and avoiding replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

