

BELZONA REPAIRS ENGINE CASING

ID: 5260

Industry: *General Industry*
Application: *ENC-Engines and Casings*
Substrate: *Cast Iron*
Products: ** Belzona 1111 (Super Metal) ,*

Customer Location: *Washington, USA*
Application Date: *1992*

Problem

The engine block had a large piece of the casing broken off.



Photograph Descriptions

- * Engine block showing missing pieces ,
- * Two pieces locked in place with studs ,
- * Completed application with Belzona 1111 ,

Application Situation

Damaged engine casing.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet ENC-1. After the proper surface preparation, the two broken pieces were locked in place using studs and Belzona 1111 was applied.

Belzona Facts

Twenty dollars worth of Belzona 1111 saved the engine block from being scrapped. The customer was fully satisfied with the results.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve