

BELZONA SAVES DRAIN DAMAGED BY CHEMICALS

ID: 5261

Industry: Food & Drink
Application: FPA-Floor Problem Areas
Substrate: Concrete and Steel
Products: * Belzona 4111 (Magma-Quartz) ,
* Belzona 4311 (Magma CR1) ,
* ,

Customer Location: Washington, USA
Application Date: 1993

Problem

Chemicals used to clean equipment in the kitchen were destroying the concrete in the drain.



Photograph Descriptions

- * Grinding the steel drain ,
- * Conditioning the concrete ,
- * Troweling in the Belzona 4111 ,
- * A coat of Belzona 4311 brushed over the drain surface ,

Application Situation

Damaged concrete in kitchen drain.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was cleaned and the steel was ground. Belzona 4111 was troweled over the area. A coat of Belzona 4311 was brushed over the surface, including the steel drain, to protect from chemical attack.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

They had been looking for a solution for several months. There were no alternatives.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

