

BELZONA IMPROVES SAFETY WITH NONSKID SURFACE

ID: 5263

Industry: Buildings & Structures

Customer Location: Washington, USA

Application: FPA-Floor Problem Areas


Application Date: 1992

Substrate: Concrete

Products: * Belzona 4411 (Granogrip),
* Belzona 9221 (Surefoot Aggregate White),

Problem

Ice build-up on the steps was causing slip problems. The chemical deicer was destroying the concrete.



Photograph Descriptions

- * Blasting the concrete ,
- * Brushing on Belzona 4411 ,
- * Sprinkling on Belzona 9221 ,
- * Completed application ,

Application Situation

Slippery steps.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The surface was blasted to remove all surface laitence. Belzona 4411 was brushed onto the surface and Belzona 9221 was spread on top.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Belzona Facts

The nonskid surface remained perfect until the building was demolished over 20 years later.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

