

# BELZONA IMPROVES SAFETY WITH GRIP SYSTEM ON STEPS

ID: 5273

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete*  
Products: *\* Belzona 4411 (Granogrip) ,*  
*\* Belzona 9221 (Surefoot Aggregate White) ,*

Customer Location: *Montana, USA*  
Application Date: *1986*

## Problem

*Stick on strips had caused tripping problems.*



## Photograph Descriptions

- \* Overview of football stadium ,
- \* Nosings blasted and masked off ,
- \* Brushing on Belzona 4411 ,
- \* Completed application, ready for repainting ,

## Application Situation

Nonslip on football stadium steps.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The step nosings were blasted. The nosings were masked off and Belzona 4411 was brushed on. Belzona 9221 was sprinkled on.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Stick on strips had proved to be ineffective, causing trip hazards. Belzona 4411 reduced the potential for accidents and provided an aesthetically pleasing finish.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

