

BELZONA PROVIDES EMERGENCY REPAIR ON A WORN CONVEYOR BELT

ID: 5277

Industry: *General Industry*

Customer Location: *BC, Canada*

Application: *SHM-Solids Handling Machinery*

Application Date: *September 2005*

Substrate: *Rubber*

Products: ** Belzona 2311 (SR Elastomer) ,
* Belzona 2911 (Elastomer QD Conditioner) ,*

Problem

A large hole had formed in this conveyor belt, causing an interruption in production.



Photograph Descriptions

- * Damaged conveyor belt, ready for repair. ,
- * Close up of repair area showing the use of the Belzona mixing surface, which was positioned underneath the belt to act as a suitable temporary backing for the repair. ,
- * Completed application. ,

Application Situation

Worn conveyor belt

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

Belzona Facts

A large hole on the conveyor belt threatened to interrupt production. The use of Belzona 2311 enabled maintenance and completed the necessary repair. Belzona reinforced the conveyor belt with a minimum amount of downtime and also prevented the loss of production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

