

BELZONA REPAIRS AND RESURFACES FLOOR


ID: 5303

Industry: Food & Drink
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4131 (Magma-Screed) ,
* Belzona 4911 (Magma TX Conditioner) ,

Customer Location: Toronto, ON, Canada
Application Date: July 2013

Problem

Over time, the floor had settled, resulting in standing water not flowing into the drain. This created an environmental hazard.



Photograph Descriptions

- * Prior to application ,
- * Preparation in progress ,
- * Completed preparation ,
- * Completed application ,

Application Situation

Floor area at a food production facility.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 for rebuilding worn and damaged floor surfaces. The surface was prepared by using a pneumatic hammer and ground to remove the existing concrete. Belzona 4911 was applied using a brush and Belzona 4131 was applied directly onto the conditioned surface, initially spreading to a general level using normal screeding techniques and then using a metal straight edge to achieve a uniform thickness.

Belzona Facts

Belzona 4131 is a two-component system for the repair and resurfacing of concrete and stonework. This high performance, non-porous resurfacing material provides excellent protection against the effects of abrasion, impact, vibration and chemical attack.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve