BELZONA PROTECTS TANK FROM CORROSION AND CHEMICAL ATTACK

ID: 5310

Industry: General Industry

Application: TCC-Tanks and Chemical Containment

Areas

Substrate: Carbon steel
Products: * Belzona 5892,

Problem

Protection of new build tank from corrosion and chemical attack.







Customer Location: Brantford, ON, Canada

Application Date: April 2014



Photograph Descriptions

- * New build tank,
- * Prior to application,
- * Application in progress,
- * Completed application ,

Application Situation

Slurry tank for water and solvents.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-3 for repairing/renewing damaged linings. Belzona 5892 was applied using a brush as a two coat system in accordance with Belzona Instructions For Use.

Belzona Facts

Originally, the specification called for an alternative protecting lining. Recent failures of that coating along with success of Belzona in other ②areas of the plant made the client switch to Belzona. Belzona 5892 is a cost-effective, two component coating system for the corrosion protection of metallic surfaces operating in immersed ②conditions. It will protect against attack from aqueous solutions and hydrocarbons operating at temperatures up to 95°C (203°F).

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®

Repair • Protect • Improve