

BELZONA EXTENDS THE LIFE OF THE ROOF

ID: 5332

Industry: *General Industry*
Application: *RPA-Roof Problem Areas*
Substrate: *Tar and Copper flashing*
Products: ** Belzona 3111 (Flexible Membrane) ,*
** Belzona 3911 (PSC Surface Conditioner) ,*
** Belzona 3921 (GSC Surface Conditioner) ,*
** Belzona 9311 (Reinforcing Sheet) ,*

Customer Location: *Great Falls, MT, USA*
Application Date: *1986*

Problem

This roof had leaked for as long as they could remember. One person speculated that it had probably leaked since it had been built, which was 1906. You can see the many protrusions through the roof, making it difficult to seal with conventional roofing products. Currently, the hot-mopped tar on the roof was seriously "alligatored".



Photograph Descriptions

- * Roof half done, showing the complicated design and many protrusions ,
- * Belzona 9311 laid out and brushing on Belzona 3111 ,
- * & 4. Completed application ,

Application Situation

Leaking roof.

Application Method

The power was cut to sections of the roof where we worked. The roof was dry brushed to remove dirt in the alligator cracks. Because the lines below the roof and overhead carried high voltage electricity, we were not allowed to use water. Belzona 3911 was brushed and rolled on all tar areas while Belzona 3921 was applied to the prepared metal bases, insulators and copper flashings around the roof edges. Belzona 9311 was laid out and the first coat of Belzona 3111 was applied with long handle brushes. The

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

second coat was brushed on the same day. The work began at one end of the roof taking 5 days to complete the job. Temperatures were over 100F on the roof. It is now 2014 and the roof has been leak free for 28 years. The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-6 & RPA-8.

Belzona Facts

Reroofing with conventional roofing materials would require tearing off the old roofing to start over on the roof deck. Belzona 3111 was easily applied over the existing aged tar, saving half the cost of conventional roofing. The owner was hoping for a ten year life span, which is their normal re-roofing schedule. Protecting the roof for 28 years and still going has saved the owners the cost of re-roofing twice.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

